



















Ax18  M6x $\frac{15}{0.6}$	Bx27  M6x $\frac{30}{1.2}$	Cx1 	Dx3 	Ex3 
Fx2 	Gx2 	Hx2 	Ix2 	Jx2 
Kx4 	Lx4 	Mx4 	FFx1 	GGx1 
HHx1 	IIx1 	JJx1 	N x1 	Ox1 
Px2 	Qx1 			





3





4



5



B  M6*30 x4

6



A  M6*15 x4

7


A  M6*15 x2




8




9




10




1




2



3





4





5

B  M6*30 x5





6

A  M6*15 x4





7


A  M6*15 x2



8



9



10

